

Dye sub printer & Heat press

Risk assessment

This table outlines the possible risks that users of this tool should bear in mind. The risk rating, likelihood, and severity are all calculated assuming that the listed control measures are followed. If you are uncomfortable with these risks, or are not confident in your ability to use this tool safely, please do not use it.

Risk rating	Likelihood	Severity	Hazard	Who may be harmed & how	Control measures
M	M	M	Skin burns from hot plate	User	Plate to be swiveled away when preparing materials. Hot plate clearly marked with warning and not to be touched. Tool only to be used with suitable materials.
M	L	H	Fire	The space, and any users in it	Area around to be kept clear of flammable materials. Tool not to be left on unattended.
M	M	M	Crush risk	User	Plate to be swiveled away until ready to press. User not to put hand between the two plates. Only one person to use press at a time.
M	H	L	Vapours may cause headache	User, users of the room	Window to be opened when in use. Other users of space to be made aware. Users instructed to stop use in case of unusual vapours or smells, especially when using new materials. Tool only to be used with suitable materials.